

Belzona Chiller Protection



The corroded water box.



Surface preparation.



Tube sheet completed.



Water box completed.

STATISTICS

CUSTOMER

Five star hotel,
Egypt

APPLICATION DATE

April 2005

SUBSTRATE

Steel

PRODUCTS

Belzona® 1341
(Supermetalglide)

APPLICATION SITUATION

Chiller unit from the hotel air conditioning plant

PROBLEM

Corrosion of the tube sheet and water box.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet HEX-3.

BELZONA FACTS

Long term protection was provided with minimum down time. The preparation and application arrangements did not disrupt the hotels operation as required by the management.